

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	IS&R	L1	0	("40372770").PN.	USPAT	2001/09/24 10:08			0
2	IS&R	L2	1	("4037270").PN.	USPAT	2001/09/24 10:28			0
3	IS&R	L3	1	("6181590").PN.	USPAT	2001/09/24 10:29			0
4	BRS	L4	1	"4709317".PN.	USPAT	2001/09/24 10:28			0
5	BRS	L5	1	"5583385".PN.	USPAT	2001/09/24 10:29			0
6	BRS	L6	1	"5617308".PN.	USPAT	2001/09/24 10:29			0
7	BRS	L7	1	"5933331".PN.	USPAT	2001/09/24 10:29			0
8	BRS	L8	203	(board with (screw or bolt)) same chip	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/09/24 10:51			0
9	BRS	L9	4	L8 and (power near chip)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/09/24 11:03			0
10	BRS	L10	416	(board with (screw\$ or bolt\$)) same chip	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/09/24 10:43		Truncation Overflow. Return string from Server is: 5'724349'	1
11	BRS	L11	85	((circuit adj board) with (screw or bolt)) same chip	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/09/24 10:52			0
12	BRS	L12	3	L11 and (power near chip)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/09/24 11:09			0
13	BRS	L13	152	(power adj chip) and (circuit adj board)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/09/24 11:10			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
14	BRS	L14	49	L13 and connector	USPAT; US-PGPPU B; EPO; 2001/09/24 JPO; 11:10 DERWENT ; IEM TDB				0